1a311747.a0a RTTUZYUW RHWIDIN0060 0311747-UUUU--RHMCSUU RHWIDIN. ZNR UUUUU R 311747Z JAN 01 ZYB FM COMVAOWINGPAC WHIDBEY ISLAND WA//N4// TO VAOWINGPAC INFO NAS WHIDBEY ISLAND WA//N41/N42// AIRTEVRON NINE CHINA LAKE CA VAORON TWO ZERO NINE MALS FOURTEEN RТ UNCLAS //N04790// MSGID/GENADMIN// SUBJ/COMVAOWINGPAC MAINTENANCE ADVISORY (CMA 04-01)// REF/A/DOC/NAVAIR/1SEP90// AMPN/NA01-85ADC-4-6, WITH CHANGE 6(1MAY99), FIG 6-27// POC/MCDANIEL/AME1 (AW)/CVWP N4234/-/TEL:DSN 257-3086// RMKS/1. THIS ADVISORY IS APPLICABLE TO ALL VAOWINGPAC ACTIVITIES AND SHALL BE REQUIRED READING FOR WORK CENTERS 020, 040, 050, 120, 13B, 210. IT CONTAINS INFORMATION ON APS 130 PNEUMATIC BOTTLES. 2. THE 100 CUBIC INCH PNEUMATIC BOTTLE AND DRAIN ASSEMBLY LISTED IN REF A, ITEM 26, IS A REFERENCE NUMBER ONLY. IF THIS PART NUMBER IS ORDERED, THE NSN CROSSES TO MULTIPLE PART NUMBERS AND A BOTTLE THAT IS NOT AUTHORIZED FOR USE IN THE EA-6B (MANUFACTURERS OTHER THAN OKDP7 OR 96487) MAY BE RECEIVED. THESE BOTTLES DO NOT HAVE A DRAIN FITTING IN THE HEAD AND HAVE AN OVERALL SHORTER LENGTH. BOTTLES WILL FIT INTO THE EA-6B AND OPERATE PROPERLY, HOWEVER DUE TO THE SHORTER OVERALL LENGTH, THE FORWARD CLAMP DOES NOT FIT PROPERLY AND MAY SLIDE DOWN THE ROUNDED END OF THE BOTTLE. 3. WHEN ORDERING REPLACEMENT APS-130 PNEUMATIC BOTTLES, ORDER ITEM 26E (P/N 12-60006-001) THIS BOTTLE WILL FIT THE ORIGINAL HEAD THAT WAS INSTALLED, HOWEVER, IF AN UNAUTHORIZED BOTTLE AND HEAD ASSEMBLY IS INSTALLED A REPLACEMENT HEAD (P/N 840327) MUST BE ORDERED ALSO. 4. CVWP HAS SUBMITTED TPDR TO REF A, CORRECTING DEFICIENCIES STATED. MAINTAIN A COPY OF THIS MESSAGE WITH AIRPAC AMMT'S. LAST CVWP ADVISORY: (CMA 03-01) DTG 2617482ZJAN01.// #0060 NNNN 

Page 1